

The cord set is designed to connect TWO 10 kV/A Restore-Lite<sup>®</sup> units to the power terminal and neutral.

FOR USE WITH 2 OF THE FOLLOWING PART NUMBERS ONLY: P80073, P80070

## **Installation and operation of Cord Sets:**

## P80018 AND P80044





SNC Manufacturing Co., Inc

101 West Waukau Avenue, Oshkosh, WI 54902 800-558-3325 or 920-231-7370 \* FAX 920-231-1090 Email: telecom@sncmfg.com Website: www.sncmfg.com

T0599

1



To Restore-Lite<sup>®</sup> Units Follow Color Code







SNC Manufacturing Co., Inc 101 West Waukau Avenue, Oshkosh, WI 54902 800-558-3325 or 920-231-7370 \* FAX 920-231-1090 Email: telecom@sncmfg.com Website: www.sncmfg.com

T0599

## 1. Attach external cord to Restore-Lite® case



- 2. Attach conductor and Twist to secure. Pig tail provided if required.
- 3. Ready for Use





**SNC Manufacturing Co., Inc** 101 West Waukau Avenue, Oshkosh, WI 54902 800-558-3325 or 920-231-7370 \* FAX 920-231-1090 Email: telecom@sncmfg.com

Website: www.sncmfg.com

T0599

