



RESTORE-LITE[®]

TEMPORARY POWER RESTORATION

The cord set is designed to connect the Restore-Lite[®] unit to the power terminal and neutral.


Installation and operation of Cord Sets:

P80017 (150 amp connectors) **P80043** (300 amp connectors)
P80023 (300 amp connectors - 6 o'clock neutral)



SNC Manufacturing Co., Inc
101 West Waukau Avenue, Oshkosh, WI 54902
800-558-3325 or 920-231-7370 * FAX 920-231-1090
Email: telecom@sncmfg.com
Website: www.sncmfg.com


1. Attach external cord to Restore-Lite[®] case



Twist Lock
Connection

2. Attach conductor and Twist to secure. Pig tail provided if required.

3. Ready for Use



Twist to Lock



Twist to Unlock



SNC Manufacturing Co., Inc
101 West Waukau Avenue, Oshkosh, WI 54902
800-558-3325 or 920-231-7370 * FAX 920-231-1090
Email: telecom@sncmfg.com
Website: www.sncmfg.com

T0596

2

