



RESTORE-LITE[®]


TEMPORARY POWER RESTORATION

The cord set is designed to connect the Restore-Lite[®] unit to the power terminal and neutral.

Installation and operation of Cord Sets:

P80065 (150 amp connectors) - **P80066** (300 amp connectors)

Cord set with Ferrules



SNC Manufacturing Co., Inc
101 West Waukau Avenue, Oshkosh, WI 54902
800-558-3325 or 920-231-7370 * FAX 920-231-1090
Email: telecom@sncmfg.com
Website: www.sncmfg.com

T0595


1. Attach external cord to Restore-Lite[®] case



**Twist Lock
Connection**

2. Attach conductor and Twist to secure.

3. Ready for Use



Twist to Lock

Twist to Unlock



SNC Manufacturing Co., Inc
101 West Waukau Avenue, Oshkosh, WI 54902
800-558-3325 or 920-231-7370 * FAX 920-231-1090
Email: telecom@sncmfg.com
Website: www.sncmfg.com

T0595

